



# EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-0262  
<http://www.EMSL.com> / [cinnmicrolab@emsl.com](mailto:cinnmicrolab@emsl.com)

Order ID: 371919522  
Customer ID: COAS80  
Customer PO:  
Project ID:

**Attn:** Marylee Morinelli  
Coastal Environmental Compliance, LLC  
PO Box 167  
Hammonton, NJ 08037-0167

Phone: (609) 820-9312  
Fax: (609) 561-6197  
Collected: 09/02/2019  
Received: 09/02/2019  
Analyzed: 09/02/2019

**Proj:** Leeds Clear 2

## Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Swab Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number:	371919522-0003	371919522-0004	371919522-0005	371919522-0006	371919522-0007
Client Sample ID:	L3	L4	L5	L6	L7
Sample Location:	MO Vent	118 Table	B. Strm Door	Nurse Wood Shelf	106 Door
Spore Types	Category	Category	Category	Category	Category
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	-	-	-	-	-
Basidiospores	-	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium	-	-	-	-	-
Cladosporium	-	-	-	-	-
Curvularia	-	-	-	-	-
Epicoccum	-	-	-	-	-
Fusarium	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	-	-	-	-	-
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	-	-	-	-	-
Insect Fragment	Rare	-	-	-	-
Pollen	-	-	-	-	-
Fibrous Particulate	Rare	-	-	-	-

**Sample Comment:** 371919522-0004 None Detected  
**Sample Comment:** 371919522-0005 None Detected  
**Sample Comment:** 371919522-0006 None Detected  
**Sample Comment:** 371919522-0007 None Detected

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.  
++ = Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.  
\* = Sample contains fruiting structures and/or hyphae associated with the spores.

Vincent Iuzzolino, M.S., Laboratory Director  
or Other Approved Signatory

No discernable field blank was submitted with this group of samples.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the result, it will be noted on the report.  
Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ AIHA-LAP, LLC--EMLAP Accredited #100194

Initial report from: 09/03/2019 10:53:48

For Information on the fungi listed in this report please visit the Resources section at [www.emsl.com](http://www.emsl.com)