

**Six Month Inspection Report
Pleasantville School District Board of Education**

Building Name/Number

Leeds Avenue School	
---------------------	--

Building Location

100 Leeds Avenue, Pleasantville, NJ 08232	
---	--

Homogeneous ID#	Material	Location	Material Cond.			Total Amt.	Damaged Amt.	Friable	Re
			TYP	DC	PDC				
01	12x12 Assumed Vinyl Asbestos Floor Tile - (1991 Building)	100 Wing, 200 Wing, 300 Wing, Library, Storage Closets, Custodial Closets	M	ND	PD	42,768 SF	0 SF	N	O&M
02	12x12 Assumed Vinyl Asbestos Floor Tile - (1983 Building)	400 Wing Classrooms, Pre-K Hallway, Main Hallway, Electrical Room, Stage Storage, Teachers' Lounge	M	D	PD	5,836 SF	8 SF	N	Minor D way, Sta O&M

*Refers to Material Type and Damage Categories

<u>T-Material Type As:</u>	<u>DC-Damage Condition</u>	<u>PD-Potential Damage Categories</u>	<u>**Response Action</u>
S - Surfacing	N - No Damage	NPD - No Potential Damage	Repair
M - Miscellaneous	D - Damage	PD - Potential Damage	Remove
T - Thermal System	SD - Significant	PSD - Potential Significant Damage	Operation & Maintenance Encapsulate

Cathy Ladden
Signature of Person Completing Report

Asbestos Inspector - ACC # 11
Title of Person Completing Report

Six Month Inspection Report Pleasantville School District Board of Education

Building Name/Number

Leeds Avenue School	
---------------------	--

Building Location

100 Leeds Avenue, Pleasantville, NJ 08232	
---	--

Homogeneous ID#	Material	Location	Material Cond.			Total Amt.	Damaged Amt.	Friable	Re
			TYP	DC	PDC				
03	Sheetrock/Wallboard – (1983 Building)	Multipurpose Room Foyer Exit, Teachers Lounge, Men’s Bathroom, Women’s Bathroom, Mechanical Room, Custodial Room, Hallway, Under Stage	M	ND	PD	1,224 SF	0 SF	N	O&M

*Refers to Material Type and Damage Categories

<u>T-Material Type As:</u>	<u>DC-Damage Condition</u>	<u>PD-Potential Damage Categories</u>	<u>**Response Action</u>
S - Surfacing	N - No Damage	NPD - No Potential Damage	Repair
M - Miscellaneous	D - Damage	PD - Potential Damage	Remove
T - Thermal System	SD - Significant	PSD - Potential Significant Damage	Operation & Maintenance Encapsulate

Cathy Ladden
Signature of Person Completing Report

Asbestos Inspector - ACC # 11
Title of Person Completing Report